

TORO®

NozzAlert™ Flow Monitoring System

MULTIPRO® SERIES SPRAYERS

F E A T U R E S

- **Peace of Mind** - Allows sprayer operator to continuously monitor flow and detect potential errors across their entire spray boom, enabling corrective action before potential misapplication and resulting turf damage..
- **Operator Alerts** - Visual and audible operator alerts for nozzle flow rate disparities caused by:
 - Totally or partially clogged nozzles
 - Worn or broken nozzles
 - Incorrect or missing nozzles
- **Customizable** - User customizable error range settings and display (i.e. with flow rate or without)
- **Compatibility** – NozzAlert is retrofittable to any Toro MultiPro Model dating back to 2006

(*Currently not compatible with GeoLink sprayer systems)




Application consistency. Always.

Never question if your MultiPro nozzles are functioning properly again.

Toro's exclusive NozzAlert Flow Monitoring system alerts the operator to improper nozzle function without ever leaving the driver's seat.

NozzAlert features a clean, intuitive 2.8" (7.1 cm) display with each individual nozzle's status conveniently on the vehicle's dash. It also offers monitoring of flow rate and will notify the operator when a nozzle experiences any flow disparities.



Call your Toro distributor at 800-803-8676