

2019/20 Toro Lawn & Garden TORO Engine Warranty Extension Promotion

December 2019

Equipment Series	Equipment Model #s	Maintenance Kit #s
Titan HD 1500 Series	74450, 74451, 74452, 74453, 74454	132-4878 (standard air filter) replaced by 139-0646 (meets latest CK-4 standard) 136-7847 (heavy-duty air filter) replaced by 139-0649 (meets latest CK-4 standard)
Titan HD/Z Master 2000 Series	74465, 74466, 74467, 74490, 74491, 74492, 74493, 74494	136-7847 replaced by 139-0649 (meets latest CK-4 standard)
TimeCutter Single Cylinder	(beginning model year 2016) 74705, 74710, 74711, 74720, 74725, 74750, 74765, 74780, 74781, 75740	136-7930 replaced by 139-0650 (meets latest CK-4 standard)
TimeCutter V-Twin	(beginning model year 2016) 74723, 74726, 74731, 74741, 74760, 74766, 74768, 74771, 74774, 74775, 74777, 74778, 74784, 74787, 74788, 74790, 74793, 74795, 75201, 75202, 75211, 75212, 75213, 75301, 75302, 75303, 75311, 75312, 75313, 75742, 75744, 75745, 75755, 75754, 75760	132-4878 (standard air filter) replaced by 139-0646 (meets latest CK-4 standard) 136-7847 (heavy-duty air filter) replaced by 139-0649 (meets latest CK-4 standard) Std on Titan, requires installation of the heavy-duty air cleaner kit (#136-7860), prior to use on TimeCutter
Walk Power Mowers	(beginning model year 2015) 20357, 20372, 20373, 20374, 20381, 20383, 20384, 21381, 21383, 21384, 21385	* 20240 -OR- 138-3208

Equipment must be registered with a copy of the receipt showing the purchase of the equipment AND maintenance kit on the same receipt.

^{*}Both kits contain a spark plug, air filter, a bottle of oil and Toro Premium Fuel Treatment. The difference between them is the size of the fuel treatment: 20240 has a 0.5 oz pouch and the 138-3208 has a 12 oz. bottle.